

CP2 / CP4S Firmware 3.9.2

Release Notes

These Release Notes contain supplemental information about firmware 3.9.2 for the CP2 dashcam and CP4S multi-cam products.

Change	What Is It?	Customer Benefits	Enablement Instructions
Current Device Storage Capacity New Feature	In conjunction with SmartAPI, CP2 and CP4S will report their current onboard storage capacity (SmartAPI release slated for late June)	Storage capacity visibility	Partners can consume this information via the GetDevice call. The Storage property will populate with the current SD card size. This value cannot be updated via the UpdateDevice API. For details on where to find device storage capacity information in the Workstation, please reference the SmartAPI June Release Notes

Coordinating Releases

CP2 & CP4S Configuration Tool 3.9.2.0, required for producing configuration files for CP2 and CP4S firmware 3.9.2.

Troubleshooting and Getting Help

- Email: smartwitness-support@sensata.com
- Phone (North/South America, APAC): +1 (312) 981-8774
- Phone (Europe): +44 (0) 1483 397005



Frequently Asked Questions

1. Are there any prerequisites for this update?

CP2 & CP4S firmware 3.9.2 may be installed on any CP2 or CP4S device in the field. We recommend adopting this update. Ensure drivers with devices on the road are notified before any firmware update initiation.

Sensata INSIGHTS believes the information in this publication is accurate as of its publication date. The information is subject to change without notice.

THE INFORMATION IN THIS PUBLICATION IS PROVIDED "AS IS". SENSATA INSIGHTS MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WITH RESPECT TO THE INFORMATION IN THIS PUBLICATION, AND SPECIFICALLY DISCLAIMS IMPLIED WARRANTIES OR MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

Use, and distribution of any Sensata INSIGHTS software described in this publication is restricted to Sensata INSIGHTS hardware.